

Government College of Engineering

Station Road, Osmanpura, Aurangabad - 431 005

Phone: (0240) 2366101, 2366221 E-Mail - principalgeca@yahoo.com

Fax: (0240) 2332835 Web - http://www.geca.ac.in

GECA/GYM/QTN/2018-19/04

Date -11/01/2019

To.

GECA Notice Board Institute Web site

Subject:- Quotation for REPAIR & RENOVATION OF SPORTS WOODEN FLOORING of Badminton Hall for Gymkhana.

Dear Sir,

You are requested to send your competitive Quotations for following items subject to the following conditions.

CONDITIONS:

- 1 Rates quoted should be FOR AURANGABAD or free delivery at the Institute inclusive of all lead and Lift.
- 2 Detailed specifications of the articles you intend to supply should be given. If not according to the specification, laid down here under.
- 3. The material/work should be supplied/completed within (07) days from the date of order. List of material is given below.
- 4. The earliest deliver period should be quoted if you cannot supply within the period mentioned above.
- 5. Quotation should be in sealed cover and superscripted as "quotations for Repair and Renovation of Flooring of Badminton Hall for gymkhana" under Gymkhana Department Due on 18-01-2019, at 4 P.M.
 - 6. Quotation should be valid for six months.
 - 7. Quotation not complying with the above conditions and incomplete once will not be considered.
 - 8. Right to reject any or all quotations rates are with the under signed.
 - 9.Rates quoted must be inclusive of All applicable Taxes and duties
 - 10. Security deposit of Rs. 20000/- shall be deposited at the office before start of work, it will be returned without interest after successful completion of work and acceptance from concerned person
 - 11 Preference will be given to suppliers with previous Badminton court repairing experienced firms, having done the same repairing at any govt / private institute/ sports clubs (attached related documents)
 - 12 Work shall be completed within stipulated period, any damage happens during repairing work shall be recovered from the supplier from security deposit.
 - 13 any supplier can visit the badminton hall during working hours for survey

REPAIR & RENOVATION OF SPORTS WOODEN FLOORING

(Note: Material & Service is as per BWF approved standards)

Sr No.	Item Description	QTY	Units	Estimated Rate	Total including GST
STEP 1	Repairing & Removing of existing damage plank and providing & fixing new plank against damaged floor planks. (21 mm thick, 63 mm + width and in random length in tongue and groove shape. The edges of the boards will have a finger lock grove and the bottom side with air pass groove - maximum four new plank per court of 15 inch each).	4896	SFT		

STEP 2	After installation the damaged planks the floor will be machine sanded in uniform level first to remove the exiting polish. After it gaps filling between the plank and the floor will be again sanded to level the gaps and floor including all material and labour.	Skiller .	100 431 03 100 100 100 100 100 100 100 100 100 1	2019	
STEP 3	Finished with double coat of PU Polishing water based polyurethane lacquer with matte finish including all labour and materials complete.				
STEP 4	Game line marking to be carried out in required colour before applying the finish coat.		-LOORM		

Yours faithfully

Principal

Four Govt. College of Engineering

Aurangabad